

KNOWN PROPOSALS FOR MORTLOCK PARK AND READE PARK

Location	Club	Facility Upgrade Proposal
Mortlock Park	Colonel Light Gardens Football Club	Upgrade Oval Lighting
Mortlock Park	Colonel Light Gardens Football Club/Goodwood Baseball Club	Upgrade Gil Langley Building, Additional Changerooms
Mortlock Park	Goodwood Baseball Club	Demolition and rebuild of baseball backstop and dugouts
Mortlock Park	Goodwood Baseball Club	Erection of temporary safety netting on freeling crescent side of oval
Mortlock Park	Goodwood Baseball Club	Upgrade Batting Tunnels
Mortlock Park	Colonel Light Gardens Football Club/Goodwood Baseball Club	New Electronic Scoreboard
Reade Park	Reade Park Tennis Club	Hardcourts 1-3 redevelopment
Reade Park	Reade Park Tennis Club	Lawn courts 13 and 14 conversion to hard courts
Reade Park	Reade Park Tennis Club	Lawn courts 1-12 fencing
Reade Park	Reade Park Tennis Club	Clubhouse improvements
Reade Park	Reade Park Tennis Club	Hereford Place entrance redevelopment
Reade Park	Colonel Light Gardens Bowling Club	Adapting energy saving initiatives
Reade Park	Colonel Light Gardens Bowling Club	Install new flood lights over bowling greens for functions
Reade Park	Colonel Light Gardens Bowling Club	Supply 3 x Liebherr 417 litre drink fridges
Reade Park	Colonel Light Gardens Bowling Club	Repair playing surface of Rink A
Reade Park	Colonel Light Gardens Bowling Club	Install grease arrestor, kitchen cabinets and appliances
Reade Park	Colonel Light Gardens Bowling Club	Replace concrete slab and install new aluminium bench seating under new verandah southern side of clubrooms
Reade Park	Colonel Light Gardens Bowling Club	Bury existing power supply from clubrooms to green keepers shed
Reade Park	Colonel Light Gardens Bowling Club	Bury existing sections of exposed water supply piping from meter to western corner of clubrooms. New

KNOWN PROPOSALS FOR MORTLOCK PARK AND READE PARK

		supply line to be installed to bowls toilets
Reade Park	Colonel Light Gardens Bowling Club	Repair ceilings in clubrooms
Reade Park	Colonel Light Gardens Bowling Club	Repair playing surface of rink B
Reade Park	Colonel Light Gardens Bowling Club	Replace bowling sheeters on northern end of Rink A and B and install aluminium bench seating
Reade Park	Colonel Light Gardens Bowling Club	Upgrade access path from Flinders Ave to clubrooms and upgrade path lighting
Reade Park	Colonel Light Gardens Bowling Club	Upgrade outdoor audio system
Reade Park	Colonel Light Gardens Bowling Club	Upgrade wheelchair access to greens
Reade Park	Colonel Light Gardens Bowling Club	Replace overhead lighting on greens
Reade Park	Colonel Light Gardens Bowling Club	Upgrade paths and retaining walls requiring replacement
Reade Park	Colonel Light Gardens Bowling Club	Upgrade vehicle access to laneway at the southern end of greens
Reade Park	Colonel Light Gardens Bowling Club	Installation of fencing to southern end of greens
Reade Park	Colonel Light Gardens Bowling Club	Upgrade western boundary fence of the bowling club and croquet club with a more traditional style heritage fence (emu wire)
Reade Park	Colonel Light Gardens Bowling Club	Upgrade sprinkler system on Rink A and B and the surrounding grassed areas. Especially if the Western Boundary fence is replaced
Reade Park	Reade Park Croquet Club	Greens and Irrigation Works
Reade Park	Reade Park Croquet Club	External lights and light pole replacement
Reade Park	Reade Park Croquet Club	Fencing along flinders ave
Reade Park	Reade Park Croquet Club	seating and shelters along flinders ave